General Environmental Incident Summary

Incident: 5440 Date/Time Notice: 6/22/2017 1200 DEM Incident No:

Responsible Party: Plains Pipeline

Date Incident: 6/21/2017 Time Incident: 1833 Duration: 5 minutes

County: Mountrail Twp: 156 Rng: 92 Sec: 25 Qtr: NW

Lat: 48.30466 Long: -102.46060 Method: Navigation quality GPS

Location Description: 1 mile south of Hwy 2 on County Road 85

Submitted By: Daniel Holli Affiliation:

Address: P.O. Box 708

City: Belfield State: ND Zip: 58622

Received By:

Contact Person: Daniel Holli

P.O. Box 708

Belfield, ND 58622

Distance Nearest Occupied Building: 1 Miles Release Contained: Yes

Type of Incident: Valve leak

Description of Released Contaminant: Crude Oil

Volume Spilled: 0.50 barrels Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

A valve leaked during refill of an above ground section of pipeline.

Risk Evaluation:

None

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

Soil

Action Taken or Planned:

Excavated soil onto plastic pending disposal

Wastes Disposal Location: Prairie Disposal

Agencies Involved:

Updates

Date: 6/22/2017 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary this spill impacted areas not associated with an Exploration and Production site. Follow-up is necessary.

Date: 7/31/2017 Status: Inspection Author: Schiermeister, Robin

Updated Volume:

Notes:

Arrived on site on 7-27-2017 at 9:01. The weather was cloudy and windy. The release occurred right in the compressor station near the GPS location given. The cause of the release was due to a mix up regarding the valves. The release was stopped from getting into their culvert by creating a make-shift berm. The contaminated dirt and gravel have been collected and stockpiled on site. A sample has been taken to classify the contamination, which will be sent to Prairie Disposal in Tioga when returned. Besides the stockpile, there were no other signs of contamination. No further follow-up is needed at this time.